


Barometric Pressure Smart Sensor (S-BPB-CM50) Quick Start

Connecting to a Station

1. Stop the station if it is logging.
2. Plug the smart sensor jack into an open smart sensor port on the station.
3. Start logging. See the station manual at www.onsetcomp.com/resources/documentation/12291-man-s-bpb for details on operating stations with smart sensors.

Mounting the Smart Sensor

- Use the cable ties to mount the smart sensor to a pole or tripod mast as shown in the photo.
- To mount the sensor on a flat, vertical surface, use the screws provided.
- The sensor must be mounted vertically to prevent water from collecting under the cap.
- Mount the sensor so that the cable is hanging straight down and create a drip-loop to prevent moisture from entering the logger connection as shown in the illustration.
- Do not screw the sensor to the side of the HOBO station case. Inserting screws in the side of the HOBO station case will violate the integrity of the unit. You can use double-sided tape.



For more information about this smart sensor, refer to the full product manual. Scan the code at left or go to www.onsetcomp.com/resources/documentation/12291-man-s-bpb.